

TABELA DE MODELOS E TAMANHOS

Ponta Montada Abrasiva

Rosa - Azul - Branca - Cinza - Verde e Preta



A-1
pol: 3/4x2.1/2
mm: 19,05x63,5
haste pol: 1/4
grão: 46



A-2
pol: 1x1.1/4
mm: 25,4x31,8
haste pol: 1/4
grão: 46



A-3
pol: 7/8x2.3/4
mm: 22,2x69,8
haste pol: 1/4
grão: 46



A-4
pol: 1.1/4x1.1/4
mm: 31,8x31,8
haste pol: 1/4
grão: 46



A-5
pol: 3/4x1.1/8
mm: 19,0x28,6
haste pol: 1/4
grão: 46



A-6
pol: 3/4x1.1/8
mm: 19,0 x28,6
haste pol: 1/4
grão: 46



A-11
pol: 13/16x1.3/4
mm: 20,6x44,4
haste pol: 1/4
grão: 46



A-12
pol: 11/16x1.1/4
mm: 17,5x31,8
haste pol: 1/4
grão: 46



A-13
pol: 1.1/8x1.1/8
mm: 28,6x28,6
haste pol: 1/4
grão: 46



A-14
pol: 11/16x7/8
mm: 17,5x22,2
haste pol: 1/4
grão: 46/60



A-15
pol: 1/4x1.1/16
mm: 6,4x27,0
haste pol: 1/4
grão: 80



A-21
pol: 1x1
mm: 25,4x25,4
haste pol: 1/4
grão: 46



A-22
pol: 3/4x5/8
mm: 19,0x15,9
haste pol: 1/4
grão: 46/60



A-23
pol: 3/4x1
mm: 19,0x25,4
haste pol: 1/4
grão: 46



A-24
pol: 1/4x3/4
mm: 6,4x19,0
haste pol: 1/4
grão: 80



A-25
pol: 1x1
mm: 25,4x25,4
haste pol: 1/4
grão: 46



A-26
pol: 5/8x5/8
mm: 15,9x15,9
haste pol: 1/4
grão: 46/60



A-31
pol: 1.3/8x1
mm: 34,9x25,4
haste pol: 1/4
grão: 46



A-32
pol: 1x5/8
mm: 25,4x15,9
haste pol: 1/4
grão: 46/60



A-33
pol: 1x1/2
mm: 25,4x12,7
haste pol: 1/4
grão: 46/60



A-34
pol: 1.1/2x3/8
mm: 38,1x9,5
haste pol: 1/4
grão: 46



A-35
pol: 1x3/8
mm: 25,4x9,5
haste pol: 1/4
grão: 46/60



A-36
pol: 1.5/8x3/8
mm: 41,3x9,5
haste pol: 1/4
grão: 46



A-37
pol: 1.1/4x1/4
mm: 31,8x6,4
haste pol: 1/4
grão: 46/60



A-38
pol: 1x1
mm: 25,4x25,4
haste pol: 1/4
grão: 46



A-39
pol: 3/4x3/4
mm: 19,0x19,0
haste pol: 1/4
grão: 46



A-40
pol: 3/4x3/4
mm: 20,0x20,0
haste pol: 1/4
grão: 46/60



B-41
pol: 5/8x5/8
mm: 15,9x15,9
haste pol: 1/8
grão: 100



B-42
pol: 1/2x3/4
mm: 12,7x9,0
haste pol: 1/8
grão: 100



B-43
pol: 1/4x5/16
mm: 6,4x7,9
haste pol: 1/8
grão: 100



B-44
pol: 7/32x3/8
mm: 7,1x9,5
haste pol: 1/8
grão: 100



B-45
pol: 3/16x5/16
mm: 4,8x7,09
haste pol: 1/8
grão: 100



B-46
pol: 1/8x5/16
mm: 3,2x7,9
haste pol: 1/8
grão: 100



B-47
pol: 1/8x5/32
mm: 3,2x4,0
haste pol: 1/8
grão: 100



B-51
pol: 7/16x3/4
mm: 11,1x9,0
haste pol: 1/8
grão: 100



B-52
pol: 3/8x3/4
mm: 9,5x19,0
haste pol: 1/8
grão: 100



B-53
pol: 1/4x5/8
mm: 6,5x15,9
haste pol: 1/8
grão: 100



B-54
pol: 1/4x1/2
mm: 6,4 x12,7
haste pol: 1/8
grão: 100



B-55
pol: 1/8x1/4
mm: 3,2x6,4
haste pol: 1/8
grão: 100



B-61
pol: 3/4x5/16
mm: 19,0x7,9
haste pol: 1/8
grão: 100



B-62
pol: 1/2x3/8
mm: 12,0x9,5
haste pol: 1/8
grão: 100



B-63
pol: 1/4x3/16
mm: 6,4x4,8
haste pol: 1/8
grão: 100



B-64
pol: 1/4x1/16
mm: 6,4x1,6
haste pol: 1/8
grão: 100



B-65
pol: 1/8x3/16
mm: 3,2x4,8
haste pol: 1/8
grão: 100



B-70
pol: 3/4x1/8
mm: 20,0x3,0
haste pol: 1/8
grão: 100



B-71
pol: 5/8x1/8
mm: 15,9x3,2
haste pol: 1/8
grão: 100



B-72
pol: 1/2x1/8
mm: 12,7x3,2
haste pol: 1/8
grão: 100



B-73
pol: 1/2x1/8
mm: 12,7x3,2
haste pol: 1/8
grão: 100



B-74
pol: 7/32x1/8
mm: 5,6x3,2
haste pol: 1/8
grão: 100



B-81
pol: 3/4x3/16
mm: 19,0x4,8
haste pol: 1/8
grão: 100



B-82
pol: 1/2x1/4
mm: 12,7x6,4
haste pol: 1/8
grão: 100



B-83
pol: 3/8x3/16
mm: 9,5x4,8
haste pol: 1/8
grão: 100








B-84
pol: 5/16x1/4
mm: 7,9x6,4
haste pol: 1/8
grão: 100



B-90
pol: 1/2x1/2
mm: 13,0x13,0
haste pol: 1/8
grão: 100



B-91
pol: 1/2x5/8
mm: 12,7x15,9
haste pol: 1/8
grão: 100





C-141
pol: 3/32x5/32
mm: 2,4 x4,0
haste pol: 1/8
grão: 100



C-142
pol: 3/32x1/4
mm: 3/32x1/4
haste pol: 1/8
grão: 100



C-143
pol: 1/8x3/16
mm: 3,2x4,8
haste pol: 1/8
grão: 100



C-144
pol: 1/8x1/4
mm: 3,2x6,4
haste pol: 1/8
grão: 100



C-145
pol: 1/8x3/8
mm: 3,2x9,5
haste pol: 1/8
grão: 100



C-146
pol: 1/8x1/2
mm: 3,2x12,7
haste pol: 1/8
grão: 100



C-147
pol: 5/32x1/32
mm: 4,0x0,8
haste pol: 1/8
grão: 100



C-148
pol: 5/32x1/16
mm: 4,0x1,6
haste pol: 1/8
grão: 100



C-149
pol: 5/32x1/4
mm: 4,0x6,4
haste pol: 1/8
grão: 100



C-150
pol: 3/16x1/16
mm: 4,8x1,6
haste pol: 1/8
grão: 100



C-151
pol: 3/16 x1/8
mm: 4,8 x3,2
haste pol: 1/8
grão: 100



C-152
pol: 3/16x1/4
mm: 4,8x6,4
haste pol: 1/8
grão: 100



C-153
pol: 3/16x3/8
mm: 4,8x9,5
haste pol: 1/8
grão: 100



C-154
pol: 3/16x1/2
mm: 4,8x2,7
haste pol: 1/8
grão: 100



C-155
pol: 13/64x1/4
mm: 5,2x6,4
haste pol: 1/8
grão: 100



C-156
pol: 1/4x1/32
mm: 6,4x0,8
haste pol: 1/8
grão: 100



C-157
pol: 1/4x1/16
mm: 6,4x1,6
haste pol: 1/8
grão: 100



C-158
pol: 1/4x1/8
mm: 6,4x3,2
haste pol: 1/8
grão: 100



C-159
pol: 1/4x3/16
mm: 6,4x4,8
haste pol: 1/8
grão: 100



C-160
pol: 1/4x1/4
mm: 6,4x 6,4
haste pol: 1/8
grão: 100



C-161
pol: 1/4x5/16
mm: 6,4x7,9
haste pol: 1/8
grão: 100



C-162
pol: 1/4x3/16
mm: 6,4x9,5
haste pol: 1/8
grão: 100



C-163
pol: 1/4x3/8
mm: 6,4x12,7
haste pol: 1/8
grão: 100



C-164
pol: 1/4 x3/4
mm: 6,4x19,0
haste pol: 1/8
grão: 80



C-165
pol: 5/16x1/16
mm: 7,9x1,6
haste pol: 1/8
grão: 100



C-166
pol: 5/16x1/8
mm: 7,9x3,2
haste pol: 1/8
grão: 100



C-167
pol: 5/16x1/4
mm: 7,9x6,4
haste pol: 1/8
grão: 100



C-168
pol: 5/16x5/16
mm: 7,9x7,9
haste pol: 1/8
grão: 100



C-169
pol: 5/16x3/8
mm: 7,9x9,5
haste pol: 1/8
grão: 100



C-170
pol: 5/16x1/2
mm: 7,9x12,7
haste pol: 1/8
grão: 100



C-171
pol: 5/16x3/4
mm: 7,9 x19,0
haste pol: 1/8
grão: 80



C-172
pol: 3/8x1/16
mm: 9,5x1,6
haste pol: 1/8
grão: 120



C-173
pol: 3/8x1/8
mm: 9,5x3,2
haste pol: 1/8
grão: 120



C-174
pol: 3/8x1/4
mm: 9,5x6,4
haste pol: 1/8
grão: 100



C-175
pol: 3/8x3/8
mm: 9,5x9,5
haste pol: 1/8
grão: 100



C-176
pol: 3/8x1/2
mm: 9,5x12,7
haste pol: 1/8
grão: 100



C-177
pol: 3/8x3/4
mm: 9,5x19,0
haste pol: 1/8
grão: 80



C-178
pol: 3/8x1
mm: 9,5x25,4
haste pol: 1/8
grão: 80



C-179
pol: 3/8x1,1/4
mm: 9,5x31,8
haste pol: 1/4
grão: 80



C-180
pol: 1/2x1/32
mm: 12,7x0,8
haste pol: 1/8
grão: 100



C-181
pol: 1/2x1/16
mm: 12,7x1,6
haste pol: 1/8
grão: 100



C-182
pol: 1/2x1/8
mm: 12,7x3,2
haste pol: 1/8
grão: 100



C-183
pol: 1/2x1/4
mm: 12,7x6,4
haste pol: 1/8
grão: 100



C-184
pol: 1/2x3/8
mm: 12,7x9,5
haste pol: 1/8
grão: 100



C-185
pol: 1/2x1/2
mm: 12,7x12,7
haste pol: 1/8
grão: 100



C-186
pol: 1/2x3/4
mm: 12,7x19,0
haste pol: 1/8
grão: 80



C-187
pol: 1/2x1
mm: 12,7x25,4
haste pol: 1/8
grão: 60



C-188
pol: 1/2x1,1/2
mm: 12,7x38,1
haste pol: 1/4
grão: 46



C-189
pol: 1/2x2
mm: 12,7x50,8
haste pol: 1/4
grão: 46



C-190
pol: 5/8x1/16
mm: 15,9x1,6
haste pol: 1/8
grão: 100



C-191
pol: 5/8x1/8
mm: 15,9x3,2
haste pol: 1/8
grão: 100



C-192
pol: 5/8x1/4
mm: 15,9x6,4
haste pol: 1/8
grão: 100



C-193
pol: 5/8x3/8
mm: 15,9x9,5
haste pol: 1/8
grão: 100



C-194
pol: 5/8x1/2
mm: 15,9x12,7
haste pol: 1/8
grão: 100



C-195
pol: 5/8x3/4
mm: 15,9x19,0
haste pol: 1/8
grão: 80



C-196
pol: 5/8x1
mm: 15,9x25,4
haste pol: 1/4
grão: 60



C-197
 pol: 5/8x2
 mm: 15,9x50,8
 haste pol: 1/4
 grão: 46




C-198
 pol: 5/8x2.1/2
 mm: 15,9x63,5
 haste pol: 1/4
 grão: 46



C-199
 pol: 3/4x1/16
 mm: 19,0x1,6
 haste pol: 1/8
 grão: 100



C-200
 pol: 3/4x1/8
 mm: 19,0x3,2
 haste pol: 1/8
 grão: 100



C-201
 pol: 3/8x1/4
 mm: 19,0x6,4
 haste pol: 1/8
 grão: 100



C-202
 pol: 3/4x3/8
 mm: 19,0x9,5
 haste pol: 1/8
 grão: 100




C-203
 pol: 3/4x1/2
 mm: 19,0x12,7
 haste pol: 1/8
 grão: 80



C-204
 pol: 3/4x3/4
 mm: 19,0x19,0
 haste pol: 1/4
 grão: 60



C-205
 pol: 3/4x1
 mm: 19,0x25,4
 haste pol: 1/4
 grão: 46



C-206
 pol: 3/4x1.1/4
 mm: 19,0x31,8
 haste pol: 1/4
 grão: 46



C-207
 pol: 3/4x1.1/2
 mm: 19,0x38,1
 haste pol: 1/4
 grão: 46



C-208
 pol: 3/4x2
 mm: 19,0x50,8
 haste pol: 1/4
 grão: 46



C-209
 pol: 3/4x2.1/2
 mm: 19,0x63,5
 haste pol: 1/4
 grão: 46




C-210
 pol: 7/8x1/16
 mm: 22,2x1,6
 haste pol: 1/8
 grão: 100



C-211
 pol: 7/8x1/8
 mm: 22,2x3,2
 haste pol: 1/8
 grão: 100



C-212
 pol: 7/8x1/4
 mm: 22,2x6,4
 haste pol: 1/8
 grão: 100



C-213
 pol: 7/8x3/8
 mm: 22,2x9,5
 haste pol: 1/8
 grão: 80



C-214
 pol: 15/16x1/4
 mm: 24,0x6,4
 haste pol: 1/8
 grão: 80



C-215
 pol: 1x1/8
 mm: 25,4x3,2
 haste pol: 1/8
 grão: 100



C-216
 pol: 1x1/4
 mm: 25,4x6,4
 haste pol: 1/8
 grão: 80



C-217
 pol: 1x3/8
 mm: 25,4x9,5
 haste pol: 1/4
 grão: 80




C-218
 pol: 1x1/2
 mm: 25,4x12,7
 haste pol: 1/4
 grão: 60




C-219
 pol: 1x3/4
 mm: 25,4x19,0
 haste pol: 1/4
 grão: 46



C-220
 pol: 1x1
 mm: 25,4x25,4
 haste pol: 1/4
 grão: 46



C-221
 pol: 1x1.1/2
 mm: 25,4x38,1
 haste pol: 1/4
 grão: 46



C-222
 pol: 1x2
 mm: 25,4x50,8
 haste pol: 1/4
 grão: 46




C-223
 pol: 1x2.1/2
 mm: 25,4x63,5
 haste pol: 1/4
 grão: 36



C-224
 pol: 1x3
 mm: 25,4x76
 haste pol: 3/8
 grão: 36



C-225
 pol: 1.1/4x1/4
 mm: 31,8x6,4
 haste pol: 1/4
 grão: 46



C-226
 pol: 1.1/4x3/8
 mm: 31,8x9,5
 haste pol: 1/4
 grão: 46



C-227
 pol: 1.1/4x1/2
 mm: 31,8x12,7
 haste pol: 1/4
 grão: 46



C-228
 pol: 1.1/4x3/4
 mm: 31,8x19,0
 haste pol: 1/4
 grão: 46



C-225
 pol: 1.1/4x1/4
 mm: 31,8x6,4
 haste pol: 1/4
 grão: 46



C-226
 pol: 1.1/4x3/8
 mm: 31,8x9,5
 haste pol: 1/4
 grão: 46



C-227
 pol: 1.1/4x1/2
 mm: 31,8x12,7
 haste pol: 1/4
 grão: 46



C-228
 pol: 1.1/4x3/4
 mm: 31,8x19,0
 haste pol: 1/4
 grão: 46



C-229
 pol: 1.1/4x1
 mm: 31,8x25,4
 haste pol: 1/4
 grão: 46



C-230
 pol: 1.1/4x1.1/4
 mm: 31,8x31,8
 haste pol: 1/4
 grão: 46



C-231
 pol: 1.1/4x1.1/2
 mm: 31,8x38,1
 haste pol: 1/4
 grão: 46



C-232
 pol: 1.1/4x2
 mm: 31,8x50,8
 haste pol: 1/4
 grão: 36



C-233
 pol: 1.1/4x2.1/2
 mm: 32x63
 haste pol: 3/8
 grão: 36



C-234
 pol: 1.1/4x3
 mm: 32x76
 haste pol: 3/8
 grão: 36



C-235
 pol: 1.1/2x1/4
 mm: 38,1x6,4
 haste pol: 1/4
 grão: 46



C-236
 pol: 1.1/2x1/2
 mm: 38,1x12,7
 haste pol: 1/4
 grão: 46



C-237
 pol: 1.1/2x1
 mm: 38,1x25,4
 haste pol: 1/4
 grão: 46



C-238
 pol: 1.1/2x1.1/2
 mm: 38,0x38,0
 haste pol: 1/4
 grão: 46



C-239
 pol: 1.1/2x2
 mm: 38,1x50,8
 haste pol: 3/8
 grão: 46



C-240
 pol: 1.1/2x2.1/2
 mm: 38,1x63,5
 haste pol: 3/8
 grão: 36



C-241
 pol: 1.1/2x3
 mm: 38,1x76,2
 haste pol: 3/8
 grão: 36



C-242
 pol: 2x1
 mm: 50,8x25,4
 haste pol: 1/4
 grão: 36



C-243
 pol: 2x1.1/2
 mm: 50,8x38,1
 haste pol: 3/8
 grão: 36



C-244
 pol: 2x2
 mm: 50,8x50,8
 haste pol: 3/8
 grão: 36



C-245
 pol: 2x2.1/2
 mm: 50,8x63,5
 haste pol: 3/8
 grão: 36



C-246
 pol: 2x3
 mm: 50,8x76,2
 haste pol: 3/8
 grão: 36